



SHADE and BLIND REPAIR

Hunter Douglas offers a “Lifetime Limited Warranty” on their products that assures your shades and blinds will be free from defects in materials and workmanship. This warranty does not apply to conditions caused by normal wear and tear (e.g. cords). This also does not include damages resulting from accidents, alterations, misuse or abuse. Listed below are restring and standard repair prices. This is a “drop off” fee and does not include service calls to pick up shade.

ASK ABOUT OUR ‘TRADE IN’ POLICY TO RECEIVE UP TO \$100 OFF A NEW SHADE OR BLIND

We are the Authorized Service Center for Hunter Douglas

As the Hunter Douglas Authorized Service Center for Northern and Central NJ, we repair shades under warranty (seven years for manual shades – five years for motorized shades) for only a nominal handling & administration fee. **We waive this fee for original owners, with proof of purchase from our stores.** (Does not include service calls.)

Diagnostic Fees, Freight, Insurance and Additional Charges

Every effort will be made to repair your shade. If it cannot be repaired, a **\$30 diagnostic fee is non-refundable**, but can be credited towards a replacement shade. The charges below apply to most repairs. If additional parts, freight or building insurance requirements require an additional charge, you will be contacted for your approval. Repairs are guaranteed for one year. **Damaged shades or those that are excessively dirty, cannot be repaired.**

'Drop off' Handling Fees for Hunter Douglas Shade & Blind Repairs <i>(Does not include service call fee)</i>	Standard or Continuous Cord (EasyRise) Lift Systems	ALL OTHER LIFT SYSTEMS Wood & Metal Blinds, 2on1, Cordless/LiteRise, UltraGlide, TopDown/BottomUp, DuoLite, Woven Woods, etc.	Motorized Shades & Skylights <i>(does not include replacement batteries or service calls)</i>
<i>Under Warrantee (Metropolitan customers)</i>	No Charge	No Charge	No Charge
<i>Under Warrantee (Purchased elsewhere)</i>	\$100	\$150	\$150
<i>Out of Warrantee and ALL Other Brands</i>	\$150	\$150	\$150 handling + Quote Will contact customer

Service Calls – ADD \$250 for service call to repair on-site or pick up, take-down, return and reinstall. Most repairs require two trips to customer home. Service calls include take down and reinstall on up to four shades. Over four shades, standard installation fees apply. **Motorized Shade service calls - \$350 for battery or \$450 for Hardwire** – does not include repair which is quoted for each job individually. AA Replacement battery wands are \$40/wand. Rechargeable wand kit \$100. **Tall window - Top of window height over 12’ = \$450 service call. High Rise service is \$450.** **Service Calls for Vertical Blinds, Luminette or other ‘track systems’ are \$350. Additional fees may apply.**

Service calls cover a 2-hour visit. Additional time is billed at \$100/hour. Parts order minimum = \$25
Warrantee handling charge minimum = \$100 or 10% of retail value of shade, whichever is greater (waived for MWF customers). Warrantee coverage does not include freight, service calls or installation.
For non-MWF customers for service in Hudson County or High Rises call Rakotex at 201-226-0027.

Temporary Shades – ADD \$10 for each temporary shade if required (discounted price for repair customers)
Rush Charges – Turnaround time is 3-4 weeks. \$50 rush surcharge – based on parts availability.
Off Site Repairs – Shades that we cannot repair in-house have an 8 week turnaround and include all Powerview, Softouch, Simplelift, Pirouette, Banded Shades, Silhouette LiteRise and Roller Shade LiteRise.
Roman Shades - We do not repair unless made by MWF. For Roman repairs contact Joel at 973- 627-5713.
For hard to find parts refer to – fixmyblinds.com or blindparts.com

HUNTER DOUGLAS CONSUMER SUPPORT 800-789-0331 CONSUMER POWERVIEW SUPPORT 844-797-8439

All Repairs are guaranteed for one year. If repaired shade fails within one year, we will either fix again or refund repair charge, less diagnostic fee. Refund does not apply to service calls. (office use – repair sku 3998; Parts sku 3120)